


## TIMBER MAT - WETLAND CROSSING



### IMPROPER INSTALLATION

- Long axis of mats is not perpendicular to travel direction
- Mats are working down into wetland causing significant disturbance and picking up mud
- Mats do not extend beyond wetland edge to solid ground



### PROPER INSTALLATION

- Correct orientation relative to travel direction
- Entire wetland is spanned, preventing rutting at ends of crossing