


Northeast Reliability Interconnect

Bangor Hydro-Electric Company



*U.S.G.S. data:
Alligator Lake and Quillpig
Mountain Quadrangles, 1988*

Existing Conditions 4A
*Panoramic view of the
Narraguagus River and Stud
Mill Road looking east. Path in
foreground is used to hand
carry canoes to the river.
Photo graphs by TJD&A,
September 29, 2004.*

Northeast Reliability Interconnect

Bangor Hydro-Electric Company



*U.S.G.S. data:
Alligator Lake and Quillpig
Mountain Quadrangles, 1988*

Photosimulation 4B
*Photosimulation of the proposed
utility corridor looking east at
the Narraguagus River and Stud
Mill Road. Photographs by
TJD&A, September 29, 2004.*